



17 / 05 / 2010

Compressor LK38 com rolamento



Código PILOTO:
14.08.3.3400-0

Outras Referências:

II-15140 knorr
002.131.15.01 MB

Aplicação:

Mercedes-Benz Motor OM 355
1569, L 1519/1520/2219/2220
LA/LB 2219
LK 1519/1520/2219
LS 1519/1520/1524/1525/1924/1924A/1929/1932/1933/1934
O 364
OH 1419/1420/1517/1518/1520/1621